

Guide to the Yale University Library Records Concerning Renovation Projects

RU 801



compiled by Daniel Hartwig

January 2008

Yale University Library
P.O. Box 208240
New Haven, CT 06520-8240
mssa.assist@yale.edu
<http://www.library.yale.edu/mssa/>

Table of Contents

Collection Overview	3
Requesting Instructions	3
Administrative Information	3
Conditions Governing Access	3
Preferred Citation	3
Processing Information	4
Separated Materials	4
Scope and Contents	4
General note	4
Arrangement	4
Collection Contents	5
Accession 1993-A-019: Renovation master plan and HVAC drawings, 1992	5
Accession 2000-A-004: Records of renovation projects in Sterling Memorial Library, 1996-1999	12
Accession 2000-A-059: Correspondence with Shepley, Bullfinch, Richardson, and Abbot (SBRA) concerning the renovation of Sterling Memorial Library, 1995-1999	13
Accession 2002-A-028: Proposal for renovation of Sterling Memorial Library and Cross Campus Library, Circa 1965	14
Accession 2002-A-028: Proposal, circa 1965	14
Accession 2006-A-006: Sterling Memorial library concept design for the Phase II renovation, 2005	15
Accession 2008-A-161: Bass Library opening student posters, 2007 October	16
Selected Search Terms	17

Collection Overview

REPOSITORY: Manuscripts and Archives
Yale University Library
P.O. Box 208240
New Haven, CT 06520-8240
mssa.assist@yale.edu
<http://www.library.yale.edu/mssa/>

CALL NUMBER: RU 801

CREATOR: Yale University. Library

TITLE: Yale University Library records concerning renovation projects

DATES: circa 1965-2007

PHYSICAL DESCRIPTION: 8.58 linear feet

LANGUAGE: English

SUMMARY: The records consist of assessments, plans, estimates, summaries, pictorial records, and architectural plans documenting the renovation of Sterling Memorial Library at Yale.

ONLINE FINDING AID: To cite or bookmark this finding aid, please use the following link: <http://hdl.handle.net/10079/fa/mssa.ru.0801>

Requesting Instructions

To request items from this collection for use in the Manuscripts and Archives reading room, please use the request links in the HTML version of this finding aid, available at <http://hdl.handle.net/10079/fa/mssa.ru.0801>.

To order reproductions from this collection, please go to http://www.library.yale.edu/mssa/ifr_copy_order.html. The information you will need to submit an order includes: the collection call number, collection title, series or accession number, box number, and folder number or name.

Key to the container abbreviations used in the PDF finding aid:

b. box
f. folder

Administrative Information

Conditions Governing Access

Access to the records is partially restricted. See Collection Contents for details.

Preferred Citation

Yale University Library Records Concerning Renovation Projects (RU 801). Manuscripts and Archives, Yale University Library.

Processing Information

Yale University records are arranged and described at the accession level by the creating office. The University Archives creates collection level descriptive records, but typically does no further arrangement and description at the accession level.

Separated Materials

Architectural drawings transferred to Record Unit 1, Architectural drawings and maps of Yale University buildings and grounds, Series II, boxes 732-740.

Scope and Contents

The records consist of assessments, plans, estimates, summaries, and pictorial records documenting the renovation of Sterling Memorial Library at Yale.

General note

Forms part of Yale Record Group 46-B (YRG 46-B), Records and materials documenting individual Yale buildings, facilities, and grounds.

Arrangement

The records are arranged by accession.

Collection Contents

Accession 1993-A-019: Renovation master plan and HVAC drawings, 1992

Restricted until Jan 1, 2028.

Master plan

1992

Volume 1

TABLE OF CONTENTS

b. 1, f. 1	I. EXECUTIVE SUMMARY
b. 1, f. 1	II. BUILDING HISTORY
	III. PHYSICAL ASSESSMENT
b. 1, f. 1	A. Exterior Walls
b. 1, f. 1	B. Windows
b. 1, f. 1	C. Rods
b. 1, f. 1	D. Structure
b. 1, f. 1	E. Heating, Ventilation and Air Conditioning
b. 1, f. 1	F. Electrical
b. 1, f. 1	G. Lighting
b. 1, f. 1	H. Telecommunications
b. 1, f. 1	I. Plumbing
b. 1, f. 1	J. Fire Protection
b. 1, f. 1	K. Vertical Transportation
b. 1, f. 1	L. Interiors
b. 1, f. 1	M. Security
b. 1, f. 1	M. Asbestos
b. 1, f. 1	IV. CODE ASSESSMENT
b. 1, f. 1	V. PROGRAM ASSESSMENT
b. 1, f. 1	VI. MASTERPLAN RECOMMENDATIONS
b. 1, f. 1	VI. SCHEDULE AND PHASING
b. 1, f. 1	VIII. COST ESTIMATES
	IX. APPENDICES
b. 1, f. 1	A. Structural Evaluation

Master plan > Volume 1 > TABLE OF CONTENTS > IX. APPENDICES (continued)

b. 1, f. 2	B. Structural Capacity Plans
b. 1, f. 2	C. Room Conditions Survey
b. 1, f. 2	D. Photographic Documentation
b. 1, f. 2	E. Historical Significance Plans
b. 1, f. 2	F. Existing Building Areas
b. 1, f. 2	G. Existing Conditions Plans
b. 1, f. 3	H. Planning Option Plan
b. 1, f. 3	I. Construction Schedules
b. 1, f. 3	J. Construction Cost Estimate
X. ADDITIONAL VOLUMES	
b. 1, f. 4	A. Building Envelope Evaluation - SML
b. 1, f. 4	B. Building Envelope Evaluation - CCL
b. 1, f. 4	C. Mechanical Systems Evaluation
b. 1, f. 4	D. HVAC Calculations
b. 1, f. 4	E. HVAC System Concept Drawings

Volume 2

TABLE OF CONTENTS

b. 1, f. 5	Executive Summary
b. 1, f. 5	1. INTRODUCTION
b. 1, f. 5	1.1 Description of Building
b. 1, f. 5	1.2 Objective
b. 1, f. 5	1.3 Scope of Work
b. 1, f. 5	1.4 Report
b. 1, f. 5	2. EXTERIOR WALLS
b. 1, f. 5	2.1 Drawings and Specification for Original Construction
b. 1, f. 5	2.2 Past Remedial Work
b. 1, f. 5	2.3 Field Observations
b. 1, f. 5	2.3.1 Survey of Interior Walls
b. 1, f. 5	2.3.2 interior Wall Probes
b. 1, f. 5	2.3.3 General Observations of Interior Walls

Master plan > Volume 2 > TABLE OF CONTENTS > 2. EXTERIOR WALLS > 2.3 Field Observations
(continued)

b. 1, f. 5	2.3.4 Observations at Probe Locations in Interior and Interior Walls
b. 1, f. 5	2.3.5 Observations During Water Testing of Exterior Walls
b. 1, f. 5	2.3.6 Observations at Perimeter Retaining Wall
b. 1, f. 5	2.4 Petrographic Analysis
b. 1, f. 5	2.5. Discussion
b. 1, f. 5	2.5.1 Interior Wall Condition and Water Penetration
b. 1, f. 5	2.5.2 Performance of Barrier Wall system
b. 1, f. 5	2.5.3 Deterioration of the Interior Stone
b. 1, f. 5	2.5.4 Perimeter Retaining Walls
b. 1, f. 5	2.5.5 Previous Remedial Maintenance
b. 1, f. 5	2.5.6 Coordination with Future Mechanical System Changes
b. 1, f. 5	2.6 Conclusions
b. 1, f. 5	2.7 Conceptual Remedial Options
b. 1, f. 5	2.7.1 Classification of Repair Needs
b. 1, f. 5	2.7.2 Exterior Wall and Retaining Walls
b. 1, f. 5	3. WINDOWS
b. 1, f. 5	3.1 Review of Original Contract Plans and Specifications
b. 1, f. 5	3.2 Performance History/Remedial Work/Upgrades
b. 1, f. 5	3.3 Information from Others
b. 1, f. 5	3.4 Field Observations
b. 1, f. 5	3.4.1 General Description
b. 1, f. 5	3.4.2 External Protective Glazing
b. 1, f. 5	3.4.3 Water-Related Damage
b. 1, f. 5	3.4.4 Window Details
b. 1, f. 5	3.5 Field Testing and Analysis
b. 1, f. 5	3.5.1 Air Infiltration Testing
b. 1, f. 5	3.5.2 Water Penetration Testing
b. 1, f. 5	3.6 Discussion
b. 1, f. 5	3.6.1 Visible Light- Transmission

Master plan > Volume 2 > TABLE OF CONTENTS > 3. WINDOWS > 3.6 Discussion (continued)

b. 1, f. 5	3.6.2 Water Penetration Resistance
b. 1, f. 5	3.6.3 Air Infiltration
b. 1, f. 5	3.6.4 Operability
b. 1, f. 5	3.6.5 Condensation
b. 1, f. 5	3.6.6 Other Considerations
b. 1, f. 5	3.7 Conclusions
b. 1, f. 5	3.7.1 Water and Air Resistance
b. 1, f. 5	3.7.2 Operability
b. 1, f. 5	3.7.3 Leaded Glass
b. 1, f. 5	3.7.4 Other Window Issues
b. 1, f. 5	3.8 Conceptual Remedial Options Analysis
b. 1, f. 5	3.9 Recommendations
b. 1, f. 5	4. ROOFING SYSTEMS
b. 1, f. 5	4.1 Drawings and Specifications for Original Construction
b. 1, f. 5	4.2 Past Remedial Work
b. 1, f. 5	4.3 Roof Survey
b. 1, f. 5	4.4 Laboratory Analysis of Roof Samples
b. 1, f. 5	4.5 Discussion
b. 1, f. 5	4.5.1 Built-up Roofing
b. 1, f. 5	4.5.2 Slate Roofing and Gutters
b. 1, f. 5	4.5.3 General Metal Work
b. 1, f. 5	4.5.4 Decorative Metal Work
b. 1, f. 5	4.6 Conclusions and Recommendations
b. 1, f. 5	4.6.1 Built-up Roofing
b. 1, f. 5	4.6.2 Slate Roofing and Gutters
b. 1, f. 5	4.6.3 General Metal Work
b. 1, f. 5	4.6.4 Decorative Metal Work
b. 1, f. 5	4.6.5 Maintenance Program
b. 1, f. 5	5. MASTER PLAN - SUMMARY AND RECOMMENDATIONS
b. 1, f. 5	5.1 Walls/Windows

Master plan > Volume 2 > TABLE OF CONTENTS > 5. MASTER PLAN - SUMMARY AND
RECOMMENDATIONS (continued)

b. 1, f. 5	5.2 Roofs
b. 1, f. 5	5.3 Summary
ILLUSTRATIONS	
b. 1, f. 5	Exterior Walls - Photos S1 through S43
b. 1, f. 5	Windows - Photos W1 through W28
b. 1, f. 5	Roofing Systems - Photos R1 through R33
APPENDICES	
b. 1, f. 5	Petrographic Analysis - S1, Pages 1 through 10
b. 1, f. 5	Original Window Schedule and Details - W1, Pages 1 through 11
b. 1, f. 5	Interior Survey, Figures 3.1 through 3.16 - W2, Pages 1 through 16
b. 1, f. 5	Window Survey, Table 3.1 - W3, Pages 1 through 10
b. 1, f. 5	Air Infiltration Testing Results, Table- 3.1.2 - W4
b. 1, f. 5	Water Test Results, Table 3.3 - W5, Pages 1 through 3
b. 1, f. 5	Decra Led Catalog information - W6, Pages 1 through 4
b. 1, f. 6	Original Roofing Detail at High Parapet - R1
b. 1, f. 6	Roof Plan by Hoffman Assoc. - R2
b. 1, f. 6	Reroofing Details by H.B. Fishman - R3, Pages 1 through 10
b. 1, f. 6	Summary of Roofing Observations and Recommendations by SGH - R4, pages 1 through 10
b. 1, f. 6	SGH Laboratory Results - R5
b. 1, f. 6	SGH Roof Drawings, Figures D.1 through D.4 - R6, Pages 1 through 4

Volume 3

TABLE OF CONTENTS

b. 2, f. 7	Executive Summary
b. 2, f. 7	1. INTRODUCTION
b. 2, f. 7	2. BACKGROUND
b. 2, f. 7	2.1 Contract Specifications
b. 2, f. 7	2.2 Architectural Plans
b. 2, f. 7	2.3 Shop Drawings

Master plan > Volume 3 > TABLE OF CONTENTS > 2. BACKGROUND (continued)

b. 2, f. 7	2.4 Reports from Others
b. 2, f. 7	2.5 Connecticut Building Code Requirements
b. 2, f. 7	3. FIELD INVESTIGATION
b. 2, f. 7	3.1 General Observations
b. 2, f. 7	3.2 Leakage survey
b. 2, f. 7	3.3 Landscaped Plaza Waterproofing
b. 2, f. 7	3.4 Entrance Court Waterproofing
b. 2, f. 7	3.5. Entrance Court Window Walls
b. 2, f. 7	3.6 Exit Courts
b. 2, f. 7	3.7 Site Wall and Stone Cladding Survey
b. 2, f. 7	4. LABORATORY ANALYSIS
b. 2, f. 7	5. DISCUSSION
b. 2, f. 7	5.1 Plaza Waterproofing
b. 2, f. 7	5.2 Window Walls
b. 2, f. 7	5.3 Deterioration of Concrete Structures
b. 2, f. 7	5.4 Deterioration of Stone Site Walk and Limestone Cladding
b. 2, f. 7	6. CONCLUSION
b. 2, f. 7	6.1 Plaza Waterproofing
b. 2, f. 7	6.2 Window Walls
b. 2, f. 7	6.3 - Stone Site Walls and Limestone Cladding
b. 2, f. 7	7. RECOMMENDATIONS
b. 2, f. 7	7.1 Near Term Repairs and Investigation
b. 2, f. 7	7.2 Long Term Repairs and investigation
b. 2, f. 8	ILLUSTRATIONS
b. 2, f. 8	Figures I through 5
b. 2, f. 8	Photos 1 through 43
b. 2, f. 8	APPENDIX
Volume 4	
TABLE OF CONTENTS	
b. 2, f. 9	I. INTRODUCTION

Master plan > Volume 4 > TABLE OF CONTENTS (continued)

b. 2, f. 9	II. EXECUTIVE SUMMARY	
b. 2, f. 9	III. HEATING, VENTILATING AND AIR CONDITION	
b. 2, f. 9	IV. ELECTRICAL	
b. 2, f. 9	V. LIGHTING	
b. 2, f. 9	VI. FIRE PROTECTION	
b. 2, f. 9	VII. SANITARY	
b. 2, f. 10	VIII. TRANSPORT AND MECHANICAL	
b. 2, f. 10	IX. OPERATIONS AND MAINTENANCE MANUALS	
b. 2, f. 10	X. OPERATING AND MAINTENANCE COSTS	
	XI. APPENDICES	
b. 2, f. 10	A. LIGHTING PHOTOGRAPHS	
b. 2, f. 11	B. HVAC ANALYSIS	
Volume 5		
TABLE OF CONTENTS		
b. 2, f. 12	I. GENERAL PARAMETERS	
b. 2, f. 13	II. ALTERNATE NO. 2 BASE BUILDING LOADS WITH FULL COOLING	
b. 2, f. 13	III. ALTERNATE NO. 2 IMPROVED BUILDING ENVELOPE WITH FULL COOLING	
b. 2, f. 14	IV. ALTERNATE NO. 3 INFILL OF COURTYARD NO.2 WITH FULL COOLING	
b. 2, f. 15	HVAC drawings	1992
b. 3	drawings	1992

**Accession 2000-A-004: Records of renovation projects in Sterling Memorial Library,
1996-1999**

0.5 linear feet (2 boxes)

Restricted until January 1, 2034.

b. 1-2

**Accession 2000-A-059: Correspondence with Shepley, Bullfinch, Richardson, and Abbot
(SBRA) concerning the renovation of Sterling Memorial Library, 1995-1999**

Restricted until Jan 1, 2034

Fax Transmittals

b.1	1995
b.1	1996
b.1	1996 Nov 1 - 1997 Jan 31
b.1	1997 Feb 1 - May 31
b.2	1997 Jun 1 - Sep 30
b.2	1997 Oct 1 - 1998 Feb 3
b.2	1998 Feb 4 - Jun 15
b.2	1998 Jun 16 - Oct 31

**Accession 2002-A-028: Proposal for renovation of Sterling Memorial Library and Cross
Campus Library, Circa 1965**

The materials are open for research.

b.1

Accession 2002-A-028: Proposal
Two copies.

circa 1965

**Accession 2006-A-006: Sterling Memorial library concept design for the Phase II
renovation, 2005**

The materials are open for research.

b.1

Sterling Memorial library concept design for the Phase II renovation

2005

Accession 2008-A-161: Bass Library opening student posters, 2007 October

The materials are open for research.

b.1	"It will change the way you...have sex"	2007 October
b.1	"It will change the way you...wipe your ass"	2007 October
b.1	"It will change the way you...shit"	2007 October

Selected Search Terms

The following terms have been used to index the description of this collection in the Library's online catalog. They are grouped by name of person or organization, by subject or location, and by occupation and listed alphabetically therein.

Subjects

Academic libraries -- Design and construction
College buildings -- Design and construction

Genres / Formats

Architectural drawings (visual works)
Architectural records

Corporate Bodies

Yale University. Library
Yale University -- Buildings